



CarBahn VANOS Spring Plate Kit for E90/E92/93 M3 S65 Engine.

The BMW S65 Engine can suffer VANOS Mechanism failure due to the plastic spring plate holding the VANOS Gear Mechanism becoming brittle over time and failing. This failure can lead to an engine failure and a very expensive engine rebuild.

These VANOS Spring Plates are designed to address and fix the Plastic Spring plate issue by replacing it with a steel spring plate.

Contains 4x CarBahn VANOS Spring Plate

NOTE: The CarBahn Vanos Spring Plates replace the OEM plastic Vanos cover and stock steel washer. BMW cam timing tools must be installed before replacement. Stock BMW Vanos bolts must be replaced.